


## Seating Tools

- Connector dedicated tools
- Upper tool for connector alignment and seating
- Lower tool for PCB support
- Quick Change style



MALE Z-PACK 2 mm HM




FEMALE Z-PACK 2 mm HM

In combination with the AMP seating presses a complete range of quick change seating tools has been developed. Both upper and lower tool, when correctly mounted on the press, are perfectly aligned ensuring a good seating, by the upper tool, and a good PCB support action by the lower tool.

Consult AMP for advice on appropriate seating tools for any application to gain optimum economy and productivity.

## Repair Tools

- Safe connector removal
- Preservation of plated through holes
- Availability of
  - housing removal tools
  - contact removal tools
  - support anvils
  - connector removal tools
- For best results on repair work always consult AMP



AMP developed a range of repair tools making it possible to remove connectors from PCB's, without damaging the plated through hole, in case a connector is damaged. Thus making it possible to avoid costly wastage of PCB's.

On the picture examples are shown specifically for certain Z-PACK 2 mm HM connectors.

Please contact AMP for further details.